




Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
ABBEYDALE PARK RISE	O/S 83	TR: Felling - Decay	Significant decay of scaffold	Prunus serrula	Plant in verge in same place o/s 83	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 9	TR: Felling, f/w damage	Lrg buttress root growing up/over edgings into f/w. Possible damage to boundary wall also.	Prunus serrula	Plant in verge o/s (between) 7-9 (same as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 20	TR: Felling - Ganoderma	Basal Ganoderma sp. decay	Prunus serrula	o/s 20, in verge, (same as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 2	TR: Felling	F/W uplifted and cracked, stem in c/w @ <5.2m	Prunus serrula	Plant in verge o/s 2 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 3	TR: Felling	Extensive f/w uplift	Prunus serrula	Plant in verge o/s 3 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 6-8, between	TR: Felling	F/W cracked and lifted by shallow roots	Prunus serrula	Plant in verge o/s- between 6-8 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 22-24, between	TR: Felling	Kerb pushed out of alignment and rooting over edgings	Prunus serrula	Plant in verge o/s- between 22-24 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 30-32, between	TR: Felling	F/W uplifted, recently repaired and cracking again	Prunus serrula	Plant in verge o/s- between 30-32 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 36	TR: Felling	F/W uplifted and cracking	Prunus serrula	Plant in verge o/s 36 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 38	TR: Felling	Kerb displaced and basal Ganoderma sp. decay	Prunus serrula	Plant in verge o/s 38 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 42-44	TR: Felling	F/W damaged and narrowed	Prunus serrula	Plant in verge o/s between 42-44 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 56-58, between	TR: Felling	Rooting over edgings into f/w	Prunus serrula	Plant in verge o/s between 56-58 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 64	TR: Felling	F/W cracked, uplifted, rooting above tarmac	Prunus serrula	Plant in verge o/s between 64-66 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 95	TR: Felling	Stem wounded with bark necrosis, poor specimen	Sorbus aucuparia	Plant in verge o/s 95 (same position as felled tree)	Crataegus laevigata 'Paul's Sc

ABBEYDALE PARK RISE	O/S 75	TR: Felling	F/W uplifted and cracked by shallow rooting	Prunus serrula	Plant in verge o/s 75 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 55	TR: Felling	F/W uplifted and cracked	Prunus serrula	Plant in verge o/s 55 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 51-53, between	TR: Felling	F/W uplifted and cracked by shallow rooting	Prunus serrula	Plant in verge o/s between 51-53 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 49	TR: Felling	F/W uplifted and cracked by shallow rooting	Prunus serrula	Plant in verge o/s 49 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ABBEYDALE PARK RISE	O/S 39	TR: Felling	Kerbs displaced, unable to replace without root damage	Prunus serrula	Plant in verge o/s 39 (same position as felled tree)	Crataegus laevigata 'Paul's Sc